
To Measure Stroke Distance on a Lever Action Rifle

1. With a ruler measure 3" from the back of the trigger



2. Mark the 3" position on both the receiver and the lever.



3. With the lever fully open, measure the distance between the two marks.

